# FUJIFILM
## Value from Innovation

**For assistance, please call 2513 2513.**

## QUICK REFERENCE FOR ApeosPort® C3060 / C2060 / C2560

7 Local User — Home — Reset

**No. and Component**

1 **<Reset> button**
2 **<Power> button**
3 **<Home> button**
4 **Data indicator**
5 **<Jobs> button**
6 **Note on status display lamp**
7 **User Login**

---

## Copy

Copy — Start
1 2 3
4 5 6
7 8 9
0 ✕

1

| Output Color | Black & White |
| 2 Sided Copying | 1→1 Sided |
| Paper Supply | Auto Select |

At [Copy] menu, select copy features, then press [Start].

### Stop Copy

Jobs — Copy 00255 ✕
Copying
Originals: 1, Quantity: 1/10
Pages: 1/1
Original Size: A4
100 %
Black & White
Next Original — 1 A4
Off | On
Collated
**System Administrator**
Pause

Resume | Delete

Select [Pause], then press [Delete].

---

## Scan

Scan — Scan
+ Add Destination
[Date & Time].pdf | .pdf

Common Features
Preview
Color Scanning | Black & White
2 Sided Scanning | 1 Sided
Resolution | 200 dpi

Select [Add Destination] to store the data in. Then select scan features and press [Scan].

### Add Destination

✕ | Favorites | All Contacts | 🔍 | ✓ OK
☐ User1 >
☐ User2

Select recipient from the [All Contacts] list. Click [OK], then select scan features and press [Scan].

### Scan Auto

Scan Auto can skip the blank pages and rotate the pages into correct orientation automatically.

ScanAuto — Send
ScanAuto
Load the original and select Send.

Scan Settings | Auto

Select recipient from the [📇], then press [Send].

### Address Book

✕ | Favorites | All Contacts | 🔍
A
B
CLARITY
elsaho
Foobar
FTP Share
aaa
Foobar

Select recipient from the [All Contacts] list.

---

## Fax

Fax — Send
+ Enter Fax Number
Preview
2 Sided Scanning | 1 Sided
Resolution | Standard (200 × 100dpi)

Select recipient from the [Enter] list. Click [OK], then select fax features and press [Send].

### Check Job Status

Jobs
Jobs
Local User—Send Fax 00119
Pending Pages: 0/1 25132877
Local User—Copy 00118
Deleted Originals: 1 Quantity: 1/10
Local User—Copy 00117
Completed Originals: 1 Quantity: 1/1
Local User—Copy 00116
Secure Print | Sample Set / Delayed Print

After fax transmission, select [Jobs] to verify the job completion status.

---