
EFI has approved the English version of this statement only. EFI did not perform the translation of the statement into Japanese. EFI is not responsible for the accuracy of the translated version and that version is not binding on EFI.

EFI Fiery Color Server for the DocuColor 5000 Digital Press
Security Measure Information

Thank you very much for using the DocuColor 5000 Digital Press.

This document provides some security measure information for using the DocuColor 5000 Digital Press, which includes a Fiery server running on Windows® XP Embedded OS.

Please check information in this document as well as the instruction manual of this product before using EFI Fiery Color Server for the DocuColor 5000 Digital Press(Fiery EX50).

- DocuColor 5000 Digital Press includes a Fiery EX50 provided by EFI, Inc. running on Windows® XP Embedded OS base (Windows® XP Embedded), which is customized by EFI for use with the Fiery color server. Thus the Fiery EX50 may be affected by various kinds of security vulnerability associated with Windows® XP Embedded. Additionally, the Fiery EX50 may be affected by viruses which take advantage of the vulnerability.
- Please understand that Fuji Xerox will ask users to take any necessary security measures such as installing and using vulnerability correction programs by themselves after installation of the product.
- EFI advises that using vulnerability-correction programs provided by Microsoft on Fiery EX50s may affect their performance. Therefore, for vulnerability-correction programs, Fuji Xerox asks users to use programs which are approved by EFI and Fuji Xerox for use with Fiery EX50s instead of Microsoft® vulnerability-correction programs. Fuji Xerox will keep providing information about the correction programs approved by EFI and Fuji Xerox to users. The information can be obtained from Fuji Xerox's official web site (<http://www.fujixerox.co.jp/>). Please apply any necessary correction programs by following the information on the website.
- EFI and Fuji Xerox authorize the installation of certain anti-virus software, listed below, onto the Fiery EX50. When installing anti-virus software, please ensure that all automatic functions of the anti-virus software like automatic real time scan, automatic scheduled scan, automatic pattern file update, etc. are disabled as they may interfere with the performance of the Fiery server. Please refer to the relevant anti-virus software manuals for the detailed instructions to invalidate all automatic functionality.
- When executing the virus scan on the Fiery EX50, the manual virus scan might be required. While the virus scan is being executed, the Fiery EX50 will not be available. EFI and Fuji Xerox recommend that you execute the scan upon confirmation of no user's job in process. As for the anti-virus software listed below, EFI and Fuji Xerox believe that the anti-virus software could be usable on the Fiery EX50 with the Auto-EXEC processing "Invalid". Neither EFI nor Fuji Xerox guarantees that any anti-virus software does not have any defect. And also, neither EFI nor Fuji Xerox tests or warranties the efficacy of any anti-virus software, including the anti-virus software listed below.
- Guidelines for running anti-virus software:
 - Anti-virus software should only be run when the Fiery EX50 is idle and not receiving jobs. Please disconnect the net connection from the Fiery EX50

- (unplug the net cable), and ensure that there is no user's job in process on Command WorkStation® when executing the virus scan with anti-virus software.
- EFI and Fuji Xerox do not support running any anti-virus software on Fiery products in auto-scan mode.
 - The anti-virus software version must be the same language version of the Fiery EX50's operating system.
 - The anti-virus software should be used for files coming into the Fiery EX50 outside of the normal print stream, including but not limited to any of the following:
 - Files in removable media (CD-ROM/R/RW, DVD-ROM)
 - Files copied to the Fiery EX50 from a shared network directory
 - All files on the Fiery EX50
 - The anti-virus software should also be configured to scan all files on the Fiery EX50 when the Fiery EX50 is not planned for use for an extended period of time.
 - In the event of infection, the recommended course of action is to remove the virus by reformatting the HDD and reloading system software.

Confirmed Anti-Virus Software on the Fiery EX50 (confirmed by Fuji Xerox)
[McAfee Virus Scan Plus 2007] (McAfee)

- As of 12/01/2006, the following security measure information is available. The following URL may be changed. Please check the latest URL.
- General information about security measure:
 - Microsoft <http://www.microsoft.com/japan/security/>
 - McAfee <http://www.mcafee.com/Japan/>
- Information about this product:
 - Fuji Xerox Co., Ltd. <http://www.fujixerox.co.jp/>

Important Note:

Installation of the anti-virus software products mentioned above in accordance with the preceding guidelines will not adversely affect the Fiery EX50's limited warranty offered by EFI. However, EFI's resolution of any bugs or issues that arise as a result of the anti-virus software may include the removal of such anti-virus software from the Fiery EX50. The information and guidelines above provide additional information to a Fiery administrator who is attempting to implement best practices to prevent the exploitation of vulnerabilities with respect to Windows® XP Embedded and the spread of viruses. This information is provided to the Fiery administrator "AS IS," is subject to change without notice, may contain errors and inaccuracies, and does not represent a commitment, warranty or representation on the part of EFI or Fuji Xerox. EFI AND FUJI XEROX DISCLAIM ALL WARRANTIES WITH RESPECT TO THIS ADDITIONAL INFORMATION, EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION THE WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT AND ANY WARRANTY ON SECURITY. EFI AND FUJI XEROX DISCLAIM ALL LIABILITY FOR DAMAGES ARISING FROM OR RELATED TO THE ADDITIONAL INFORMATION AND SHALL IN NO EVENT BE LIABLE FOR LOSS OF PROFITS, INACCURACY OF DATA, OR INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES, EVEN IF EFI AND FUJI XEROX HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

EFI and Fiery and Command WorkStation are registered trademarks of EFI in the U.S. Patent and Trademark Office and/or certain other foreign jurisdictions. Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.